CCTV Inspections
Naugatuck River Levee System
Ansonia, CT
August-September 2010

FOR:

Milone and MacBroom
99 Realty Drive
Cheshire, CT 06410

HEITKAMP

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	SEG1/2	ANSONIA-DERBY CT	UTILITY LAYOUY NO.7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/26/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	45.9		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	SEG1/2	2010/08/26	08:50	UTILITY LAYOUY NO.7	ANSONIA-DERBY CT

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH1			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH2					D		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	45.9	45.9			450-1 VTR 0:00:00-0:03:35

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
45.9	187	AMH											MH2

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	SEG3/1	ANSONIA-DERBY	UTILITY LAYOUT NO.7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/26/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	905.5		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	SEG3/1	2010/08/26	08:59	UTILITY LAYOUT NO.7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH3			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH1					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	905.5	905.5			450-1 VTR 0:03:35-/450-3 vtr 0:10:32-0:18:47

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
336.1	1405	TFA				6				12			CLEAN OUT
201.4	568	TFA				6				12			
569.4	508	ACOM											clean out

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	SEG4/5	ANSONIA-DERBY	UTILITY LAOUT NO.6/7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		48	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	304.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	SEG4/5	2010/08/27	08:36	UTILITY LAOUT NO.6/7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH4			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH5					D		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	304.0	304.0			450-1 VTR 0:45:25-0:49:15

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
304.0	235	AMH											MH5

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH5/PS1	ANSONIA-DERBY	UTILITY LAYOUT NO.7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		54	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	517.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH5/PS1	2010/08/27	08:49	UTILITY LAYOUT NO.7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH5			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
PS1					D		54

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	517.0	517.0			450-1 VTR 0:49:15-0:58:08

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		J	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
517.0	548	AMH											PS1

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH7/4	ANSONIA-DERBY	UTILITY LAYOUT N0.6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		48	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	409.8		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH7/4	2010/08/27	09:38	UTILITY LAYOUT N0.6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH7			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH4					U		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	409.8	409.8			450-1 VTR 0:58:08-1:06:51

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
40.1	146	CL		S1						12			
56.4	146	CL		F1						12			
409.8	533	AMH											MH7

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH8/7	ANSONIA-DERBY	UTILITY LAYOUT NO.6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		42	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	258.6		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH8/7	2010/08/27	09:52	UTILITY LAYOUT NO.6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH8			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH7					U		42

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	368.0	258.6			450-1 VTR 1:06:51-/450-2 0:26:05

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
121.3	121	TFA				24				9			

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH9/8	ANSONIA-DERBY	UTILITY LAYOUT NO.6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		36	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	89.1		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH9/8	2010/08/27	11:40	UTILITY LAYOUT NO.6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH9			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH8					D		36

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	89.1	89.1			450-1 VTR 1:07:52 -1:10:06

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
89.1	146	AMH											MH8

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH10/9	ANSONIA-DERBY	UTILITY LAYOUT NO5/6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		30	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	200.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH10/9	2010/08/27	12:10	UTILITY LAYOUT NO5/6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH10			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH9					U		30

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	200.0	200.0			450-1 VTR 1:13:24-

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
200.0	260	AMH											MH10

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	PS1/STR7	ANSONIA-DERBY	UTILITY LAYOUT N0.7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/27/2010		54	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	305.3		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	PS1/STR7	2010/08/27	13:42	UTILITY LAYOUT N0.7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	PS1			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
STR7					U		54

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	291.6	305.3			450-1 VTR 1:18:00-/450-2 0:00:00-0:10:14

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
100.9	103	TBA				18				3			
110.5	156	TBA				10				2			
291.6	443	AMH											STR7

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	SEG6/3	ASONIA-DERBY	UTILITY LAYOUT N0.7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/30/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	417.5		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	SEG6/3	2010/08/30	08:31	UTILITY LAYOUT N0.7	ASONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	CO7			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH3					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	417.5	417.5			450-1 VTR 1:28:21-

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
61.7	158	TFA				6				12			CLEAN OUT
63.6	200	JSM			M								
248.7	921	RFJ							J	3			
344.5	762	MSA											CRAWLER COULD NOT PULL CABLE
417.5	394	ACOM											CO7

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	PS1/OF1	ANSONIA-DERBY	UTLILTY LAYOUT NO7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/30/2010	6	6	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	148.4		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	PS1/OF1	2010/08/30	11:23	UTLILTY LAYOUT NO7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	PS1			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
OF1					D		6

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
6	S	RCP			148.4	148.4			450-2 0:10:15-0:13:22

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
131.2	112	AOC											
148.4	156	ADP											

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH2/PS1	ANSONIA-DERBY	UTILITY LAYOUT NO7

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/30/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	10.6		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH2/PS1	2010/08/30	11:45	UTILITY LAYOUT NO7	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH2			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
PS1					D		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		5.0	10.6	10.6			450-2 VTR 0:13:22-0:15:51

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
8.4	77	H								12			
10.3	109	AMH											PS1

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	CO7/MH7	ANSONIA-DERBY	UTILITY LAYOUT NO6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/30/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	80.7		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	CO7/MH7	2010/08/30	12:45	UTILITY LAYOUT NO6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	CO7			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH7					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			80.7	80.7			450-2 VTR 0:17:44-0:22:14

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
80.7	278	ACOM											CO7

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH11/10	ANSONIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		30	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	47.1		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH11/10	2010/08/31	07:55	UTILITY LAYOUT NO5	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH11			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH10					D		30

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	47.1	47.1			450-2 VTR 0:26:05-0:27:45

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		J	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
47.1	109	AMH											MH10

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH13/12	ANSONIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		30	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	58.9		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH13/12	2010/08/31	09:09	UTILITY LAYOUT NO5	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH13			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH12					U		30

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	58.9	58.9			450-2 VTR 0:33:08-

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		J	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
58.9	160	AMH											MH13

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH14/13	ANSOSIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		18	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	360.9		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH14/13	2010/08/31	11:10	UTILITY LAYOUT NO5	ANSOSIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH14			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH13					U		18

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		8.0	360.9	360.9			450-2 VTR 0:35:37-0:43:42

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		H	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
360.9	493	AMH											MH14

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH15/13	ANSONIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		12	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	23.7		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-70401474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH15/13	2010/08/31	11:50	UTILITY LAYOUT NO5	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH15			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH13					D		12

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	23.7	23.7			450-2 VTR 0:43:42-0:46:25

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
23.7	178	AMH											+MH13

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH16/15	ANSONIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	369.9		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH16/15	2010/08/31	12:08	UTILITY LAYOUT NO5	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH16			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH15					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	369.9	369.9			450-2 VTR 0:46:25-1:28:43

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N				

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
369.9	377	ACOM											CO14

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH15/6	ANSONIA-DERBY	UTILITY LAYOUT N05/6

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	492.7		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH15/6	2010/08/31	13:32	UTILITY LAYOUT N05/6	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH15			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH6					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	460.0	492.7			450-2 VTR 1:28:43-1:50:21

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
331.3	1031	MSA											COULD NOT CRAWL ANY MORE
160.8	302	MSA											OVERLAPPED TV

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH6/8	ANSONIA-DERBY	UTILITY LAYOUT N06

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	67.8		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-70401474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH6/8	2010/08/31	15:02	UTILITY LAYOUT N06	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH6			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH8					D		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	67.8	67.8			450-2 VTR 1:50:21-END

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
67.8	156	AMH											MH8

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH6/CO7	ANSONIA-DERBY	UTILITY LAYOUT N06

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	372.6		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH6/CO7	2010/08/31	15:10	UTILITY LAYOUT N06	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH6			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
CO7					D		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	372.6	372.6			450-3 VTR 0:00:00-0:10:32

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
372.6	591	ACOM											CO7

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH14/CO14	ANSONIA-DERBY	UTILITY LAYOUT NO5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/1/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	16.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-174		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH14/CO14	2010/09/01	10:31	UTILITY LAYOUT NO5	ANSONIA-DERBY

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH14			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
CO14					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	16.0	16.0			450-3 VTR 0:18:47-0:20:06

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
16.0	89	ACOM											CO14

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH17/CO17C	DERBY-ANSONIA	UTILITY LAYOUT NO8

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/1/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	431.5		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH17/CO17C	2010/09/01	11:04	UTILITY LAYOUT NO8	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH17			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
CO17A					U		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	431.5	431.5			450-3 VTR 0:20:06-0:36:30

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
225.4	737	ACOM											CO17
431.5	996	ACOM											CO17A

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH17/18	DERBY -ANSONIA	UTILITY LAYOUT N08

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/1/2010		8	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	355.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH17/18	2010/09/01	12:36	UTILITY LAYOUT N08	DERBY -ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH17			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH18					D		8

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP		10.0	355.0	355.0			450-3 VTR 0:36:30-0:46:31

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		J	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
205.5	272	ACOM											CO18
355.0	577	AMH											MH18

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH20/19	DERBY -ANSONIA	UTILITY LAYOUT N08

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/1/2010		48	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	357.5		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH20/19	2010/09/01	14:10	UTILITY LAYOUT N08	DERBY -ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH20			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH19					U		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	357.5	357.5			450-3 VTR 0:46:31-0:56:49

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N				

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
157.0	113	DSGV					20		3	9			
357.5	637	AMH											MH20

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH19/OF2	DERBY-ANSONIA	UTILITY LAYOUT NO8

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/1/2010	4	4	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	160.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH19/OF2	2010/09/01	15:08	UTILITY LAYOUT NO8	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH19			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
OF2					D		4

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
4	S	RCP		5.0	160.0	160.0			450-3 VTR 0:56:49-1:00:46

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
130.5	125	AOC											
160.0	205	ADP											OF2

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH21/20	DERBY-ANSONIA	UTILITY LAYOUT NO8

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		48	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	305.2		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH21/20	2010/09/02	08:23	UTILITY LAYOUT NO8	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH21			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH20					D		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			305.2	305.2			450-3 VTR 1:00:46-1:05:08

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N				

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
305.2	231	AMH											MH20

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH22/21	DERBY-ANSONIA	UTILITY LAYOUT NO8

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		48	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	462.9		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	MH22/21	2010/09/02	08:56	UTILITY LAYOUT NO8	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	MH22			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH21					U		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	462.9	462.9			450-3 VTR 1:05:08-1:11:33

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descriptor	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
462.9	393	AMH											MH22

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	STR8/MH22	DERBY-ANSONIA	UTILITY LAYOUT NO8

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		48	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Upstream	178.4		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	STR8/MH22	2010/09/02	09:07	UTILITY LAYOUT NO8	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	STR8			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
MH22					U		48

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	RCP		5.0	178.4	178.4			450-3 VTR 1:11:33-1:17:15

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
155.3	151	ACB											STR8
155.3	0	MSC				36							
178.4	323	ACB											

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	WELL 1/ B1	DERBY-ANSONIA	DERBY SHEET 5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		10	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	32.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	WELL 1/ B1	2010/09/02	10:12	DERBY SHEET 5	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	WELL 1			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
B1					D		10

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			32.0	32.0			450-3 VTR 1:17:15:1:21:54

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
32.0	0	AWW											

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	WELL2/B2	DERBY-ANSONIA	DERBY SHEET 5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		10	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	30.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	WELL2/B2	2010/09/02	10:37	DERBY SHEET 5	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	WELL 2			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
B2					D		10

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			30.0	30.0			450-3 VTR 1:21:54-1:23:54

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N				

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	Value %	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
30.0	126	AWW											WELL2

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	WELL3/B3	DERBY-ANSONIA	DERBY SHEET 5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		10	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	28.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	WELL3/B3	2010/09/02	10:49	DERBY SHEET 5	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	WELL3			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
B3					D		10

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			28.0	28.0			450-3 VTR 1:23:54-1:26:42

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
28.0	159	AWW											WELL3

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	WELL4/B4	DERBY-ANSONIA	DERBY SHEE 5

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010		10	CMP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	30.0		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	WELL4/B4	2010/09/02	11:15	DERBY SHEE 5	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	WELL4			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
B4					D		10

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
	C	CMP			30.0	30.0			450-3 VTR 1:26:42-1:28:28

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
30.0	112	AWW											WELL4

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	INLT1/OF3	DERBY-ANSONIA	DERBY SHEET 4

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
9/2/2010	6	6	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	133.2		



NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219

HEITKAMP

PACP Sewer Report

Surveyors Name	and Certificate Number	System Owner	Survey Customer	Drainage Area	Sheet No.
JOSEPH ASSARD	U-704-1474		MILONE & MACBROOM		1

P/O No.	Pipeline Segment Reference	Date	Time	Location (Street Name and Number)	Locality
	INLT1/OF3	2010/09/02	12:02	DERBY SHEET 4	DERBY-ANSONIA

Further Location Details	Upstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade
	INLT1			

Downstream Manhole Number	Rim to Invert	Grade to Invert	Rim to Grade	Use of Sewer	Direction	Flow Control	Height
OF3					D		6

Width	Shape	Material	Ln. Method	Pipe Joint Length	Total Length	Length Surveyed	Year Laid	Year Rehabilitated	Tape/Media Number
6	S	RCP			133.2	133.2			450-3 VTR 1:28:28-1:33:27

Purpose	Sewer Category	Pre-Cleaning	Cleaned	Weather	Location Code	Additional Information
		N	2010/08/26			

Distance (Feet)	Video Ref.	Group/ Descripto	Modifier/ Severity	Continuous Defect	S/M/L	Value Inches 1st	Value Inches 2nd	%	Joint	Circumferential Location at	Circumferential Location to	Image Ref.	Remarks
130.3	236	AOC											
133.2	276	ADP											

NEPCCO Division Heitkamp, Inc.
99 Callender Road
Watertown, CT 06795
Phone: (860) 274-5469
Fax: (860) 945-3219


HEITKAMP

TV Inspection with Pipe-Run Graph

Project Name:	Asset ID:	City:	Address:
DERBY-ANSONIA, CT	MH12/11	ANSONIA-DERBY	UTILITY LAYOUT N05

Date	Pipe Width:	Pipe Height:	Pipe Type:	Surface Condition:
8/31/2010		30	RCP	

Direction:	Surveyed Footage:	Weather	Tape/Media #
Downstream	21.2		



Burning at 9.23.2010 10.03.22 AM

Burning started at 9/23/2010 10:03:22 AM
Destination: DVD, D:\

Export started at 09/23/10 10:03:22
Local database: G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\DERBY-ANSONIA.mdb
Export finished at 09/23/10 10:03:22
Burning disk 1 of 2, label "Ansonia-VBO01"
Video files burned:
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT- MH1-CO1-UTILITY LAYOUT NO7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-CO7-MH3-UTILITY LAYOUT N0.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-CO7-MH7-UTILITY LAYOUT NO6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-INLT1-OF3-DERBY SHEET 4.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH1 -MH2-UTILITY LAYOUY NO.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH10-MH9-UTILITY LAYOUT NO5_6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH11-MH10-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH12-MH11-UTILITY LAYOUT N05.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH12-MH11-UTILITY LAYOUT N050.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH13-MH12-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH14-CO14-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH14-MH13-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH15-MH13-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH15-MH6-UTILITY LAYOUT NO5_6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH15-MH6-UTILITY LAYOUT NO5_60.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH16-MH15-UTILITY LAYOUT NO5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH16-MH15-UTILITY LAYOUT NO51.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH17-CO17A-UTILITY LAYOUT NO8.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH17-MH18-UTILITY LAYOUT N08.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH19-OF2-UTILITY LAYOUT NO8.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH2-PS1-UTILITY LAYOUT NO7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH20-MH19-UTILITY LAYOUT N08.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH21-MH20-UTILITY LAYOUT NO8.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH22 -MH21-UTILITY LAYOUT NO8.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH3-MH1 -UTILITY LAYOUT NO.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH3-MH1 -UTILITY LAYOUT NO.70.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH3-MH1 -UTILITY LAYOUT NO.71.mpg

Burning at 9.23.2010 10.03.22 AM
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH4-MH5-UTILITY LAOUT NO.6_7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH5-PS1-UTILITY LAYOUT NO.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH6- CO7-UTILITY LAYOUT N06.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH6-MH8 -UTILITY LAYOUT N06.mpg
NO.6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH8 -MH7-UTILITY LAYOUT
NO80.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-STR8-MH22 -UTILITY LAYOUT
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-WELL 1-B1-DERBY SHEET 5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-WELL4-B4-DERBY SHEE 5.mpg
Burning disk 2 of 2, label "Ansonia-VBO02"
Video files burned:
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH6-MH3-UTILITY LAYOUT N0.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH6-MH3-UTILITY LAYOUT N0.71.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH7-MH4-UTILITY LAYOUT N0.6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH8 -MH7-UTILITY LAYOUT
NO.60.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH8 -MH7-UTILITY LAYOUT
NO.61.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-MH9-MH8 -UTILITY LAYOUT
NO.6.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-PS1-OF1-UTLILTY LAYOUT NO7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-PS1-STR7-UTILITY LAYOUT N0.7.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-PS1-STR7-UTILITY LAYOUT
N0.70.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-STR8-MH22 -UTILITY LAYOUT
NO8.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-WELL 1-B1-DERBY SHEET 50.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-WELL 2-B2-DERBY SHEET 5.mpg
G:\10-03-3060 - Milone and MacBroom - Ansonia-Derby\Media\Video\DERBY-ANSONIA, CT-WELL3-B3 -DERBY SHEET 5.mpg
Burning finished at 9/23/2010 10:16:50 AM