

# Service Request 5933

## Record Info

<b>Request ID:</b>	5933	<b>Request Type:</b>	- Bypass / SSO 5 Day Report Form
<b>Priority:</b>	2	<b>Entered By:</b>	Edward_Abel
<b>Date Submitted:</b>	5/1/2024 5:25:00 AM	<b>Cross Street:</b>	Factory St
<b>Address:</b>	1 Caroline St Derby		
<b>District:</b>			
<b>Comments:</b>	Our back up aeration blower not running. Main blower is out of service waiting on repairs. A crew is on their way to the plant.		
<b>Private Notes:</b>			
<b>Reporting Utility:</b>	DERBY		
<b>Incident type:</b>	Sewage Bypass		
<b>Weather Conditions:</b>	Dry		
<b>Date Bypass Began or Discovered:</b>	5/1/2024		
<b>Approximate Time Event Started:</b>	04:45 AM		
<b>Location of Bypass:</b>	Treatment Plant		
<b>Private backups caused by Sewer Main Blockage:</b>	No		
<b>Type of Bypass:</b>	Partially Treated Raw Sewage		
<b>Cause of Bypass:</b>	Mechanical Equipment Failure		
<b>Cause of Bypass Other Explanation:</b>	Our back up aeration blower not running. Main blower is out of service waiting on repairs. A crew is on their way to the plant.		
<b>How was incident discovered:</b>	Auto dialer alarm		
<b>Estimated Quantity or Rate of Discharge:</b>	25,000 - 50,000 gallons		
<b>How was estimated quantity or rate determined:</b>	visual of effluent discharge		
<b>Reach Waterbody:</b>	Yes		
<b>Waterbody Name:</b>	Housatonic River		
<b>If Reach Water Date time and how CEO notified:</b>	email		
<b>Closest Address or MH for Reference:</b>	1 Caroline Street.		
<b>Date Bypass Ended:</b>	5/1/2024		
<b>Approximate Time Event Ended:</b>	05:15 AM		
<b>Final Quantity or Volume:</b>	Between 25,000 & 50,000		
<b>How was final quantity or volume determined:</b>	A rough calculation of the total daily effluent discharge against the duration of the offline blower.		
<b>How was incident resolved:</b>	The blower tripped out due an issue with the harmonic guard. The harmonic guard was by-passed breaker was reset.		
<b>DEEP Final Gallons Numbers Only:</b>			

**DEEP Private Caused by Sewer Main:**  
**DEEP Refer for Enforcement:**  
**DEEP Reviewer:**

Submitter Info

<b>Name:</b>	Abel, Edward R	<b>Email:</b>	eabel@derbyct.gov
<b>Address:</b>	1 Caroline Street Derby, CT 06418		
<b>Phone #:</b>	203-673-7128	<b>Extension:</b>	
<b>Alt. Phone #:</b>	<b>Extension:</b>		
<b>Notify:</b>	<input checked="" type="checkbox"/>		
<b>Please verify this info is correct:</b>	Verify		

Activity List

<b>Date:</b>	5/1/2024 5:25:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	Service Request Open - ID 5933 Routed To: Derby, DoAg Aquaculture, DPH Recreation, EPA - Jack, Supervisor-Asst Director Comments: Our back up aeration blower not running. Main blower is out of service waiting on repairs. A crew is on their way to the plant.
<b>Date:</b>	5/1/2024 5:25:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	An automated email has been sent to the submitter(s): eabel@derbyct.gov
<b>Date:</b>	5/6/2024 11:42:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	Service request type changed from "- Bypass / SSO 2 Hour Report Form" to "- Bypass / SSO 5 Day Report Form" by Edward_Abel
<b>Date:</b>	5/6/2024 11:42:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	Service Request rerouted to Derby, DoAg Aquaculture, DPH Recreation, EPA - Jack, Supervisor-Asst Director
<b>Date:</b>	5/6/2024 11:46:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	The breaker for the blower tripped out due to an issue with the harmonic guard. The harmonic guard was by-passed and the breaker was reset.
<b>Date:</b>	5/16/2024 11:48:00 AM
<b>User:</b>	Edward_Abel
<b>Comments:</b>	Service request printed by Edward_Abel